## REPORT OF CHANNEL CONDITIONS 100 TO 400 FEET WIDE

(EP 1130-2-520)

PAGE 1 OF

1

DATE
23 September 2008

TO: Navigation Interests FROM:

U.S. Army Engineer District, Baltimore

P.O. Box 1715

Baltimore, Maryland 21203-1715

RIVER/HARBOR NAME AND STATE Potomac River Maryland					MINIMUM DEPTHS IN CHANNEL ENTERING FROM SEAWARD		
NAME OF CHANNEL	DATE	AUTHORIZED PROJECT			LEFT	RIGHT	
	OF SURVEY	WIDTH (feet)	LENGTH (miles)	DEPTH (feet)	OUTSIDE QUARTER (feet)	MIDDLE HALF (feet)	OUTSIDE QUARTER (feet)
Nanjemoy Bar 0+000 - 5+200		200	1	24	22	22	22
Surveyed on 9 and 11 Sep 2008							

REMARKS (Continue on reverse)

All depths refer to MLLW for the 1983-2001 tidal epoch. This information represents the results of surveys made on the dates shown and can only be as indicating the general results of surveys made at that time. Channel length is reported to the nearest mile. Actual length is 0.98 miles. Depths are reported to the nearest foot.

LQ=E1280815.85, N264701.98 (22.0')

MH=E1281028.12, N264718.48 (22.0')

RQ=E1280466.22, N264454.24 (22.1')